YOUR ONESURVEY HOME REPORT

ADDRESS

26 Spires Crescent Nairn IV12 5PZ

PREPARED FOR

Anthony Cassar-Torreggiani

INSPECTION CARRIED OUT BY:



SELLING AGENT:

Moving Made Easy

HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Index of Documents			
Single Survey	Final	Inverness - Allied Surveyors Scotland Plc	29/01/2020
Mortgage Certificate	Final	Inverness - Allied Surveyors Scotland Plc	29/01/2020
Property Questionnaire	Final	Mr. Anthony Cassar- Torreggiani	28/01/2020
EPC	File Uploaded	Inverness - Allied Surveyors Scotland Plc	29/01/2020

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is essential that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

PART 1

SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Customer	Mr. Anthony Cassar-Torreggiani
Selling address	26 Spires Crescent Nairn IV12 5PZ
Date of Inspection	28/01/2020
Prepared by	Keith Campbell, Assoc.RICS Inverness - Allied Surveyors Scotland Plc

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 \square

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller:
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities:
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a detached one and half storey dwelling house having the benefit of surrounding garden grounds, off street parking and an attached single car garage.
Accommodation	The accommodation may be summarised as follows: Ground Floor - Hall, Living Room, Kitchen/Dining Room, Utility, Bedroom and en-suite Shower Room. First Floor - Landing, three Bedrooms and Bathroom.
Gross internal floor area (m2)	Approximately 133 square metres.
Neighbourhood and location	The property forms part of an established residential area of similar style and age properties located on the fringes of Nairn, close to Nairn Dunbar Golf Club. All local amenities can be found nearby.
Age	15 years.
Weather	Weather conditions were dry and bright at the time of inspection.
Chimney stacks	There are no chimney stacks.
Roofing including roof space	The roof structure is of a traditional pitched design, clad externally with concrete interlocking tiles, over timber trusses and undertile felt.


Internally, the apex roof space was accessed via a ceiling hatch in the landing and this found the area to be insulated with approximately 200mm thick glasswool quitting. This roof space was partially floored and full of stored items at the time of inspection. Stoping roofs were visually inspected with the aid of binoculars where required. The rainwater goods comprise PVC gutters and downpipes. Visually inspected with the aid of binoculars where required. Main walls The main outer walls are of cavity timber frame and rendered block or facing brick construction, plasterboard lined internally. Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. Windows, external doors where not exposed or inspected. Windows throughout comprise UPVC double glazed units. The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations There are no conservatories or porches. Conservatories / porches There are no conservatories or porches. There are no conservatories or porches. There are no conservatories or porches. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges. Visually inspected.		Ţ
Rainwater fittings The rainwater goods comprise PVC gutters and downpipes. Visually inspected with the aid of binoculars where required. The main outer walls are of cavity timber frame and rendered block or facing brick construction, plasterboard lined internally. Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. Windows, external doors and joinery Windows throughout comprise UPVC double glazed units. The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where keys were available. Random windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		hatch in the landing and this found the area to be insulated with approximately 200mm thick glasswool quilting. This roof space was partially floored and full of stored items at the time of inspection. Sloping roofs were visually inspected with the aid of binoculars
Main walls The main outer walls are of cavity timber frame and rendered block or facing brick construction, plasterboard lined internally. Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. Windows, external doors and joinery Windows throughout comprise UPVC double glazed units. The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		where required.
The main outer walls are of cavity timber frame and rendered block or facing brick construction, plasterboard lined internally. Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. Windows, external doors and joinery Windows throughout comprise UPVC double glazed units. The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries Doutside areas and boundaries are formed in timber post and panel fencing or hedges.	Rainwater fittings	The rainwater goods comprise PVC gutters and downpipes.
rendered block or facing brick construction, plasterboard lined internally. Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. Windows, external doors and joinery Windows throughout comprise UPVC double glazed units. The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries Boundaries are formed in timber post and panel fencing or hedges.		Visually inspected with the aid of binoculars where required.
Windows, external doors and joinery Windows throughout comprise UPVC double glazed units. The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. There are no conservatories or porches. Communal areas There are no communal areas. Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	Main walls	rendered block or facing brick construction, plasterboard
The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas There are no communal areas. Garages and permanent outbuildings Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		, , , , , , , , , , , , , , , , , , ,
The main entrance door is UPVC double glazed and the external fascias are formed in white PVC. Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. There are no conservatories or porches. Communal areas There are no communal areas. Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	-	Windows throughout comprise UPVC double glazed units.
available. Random windows were opened and closed where possible. Doors and windows were not forced open. External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas There are no communal areas. Garages and permanent outbuildings Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	, , , , ,	
External decorations As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas There are no communal areas. There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		
As above, walls are rendered or facing brick and fascias are formed in white PVC. Visually inspected. There are no conservatories or porches. Communal areas There are no communal areas. Garages and permanent outbuildings Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		Random windows were opened and closed where possible.
formed in white PVC. Visually inspected. Conservatories / porches There are no conservatories or porches. Communal areas There are no communal areas. There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		Doors and windows were not forced open.
Conservatories / porches There are no conservatories or porches. There are no communal areas. There are no communal areas. There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	External decorations	•
Communal areas There are no communal areas. There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		Visually inspected.
Garages and permanent outbuildings There is an attached single car garage which has a floor area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		There are no conservatories or porches.
area extending to approximately 17 square metres. Within the grounds, there is a timber and felt garden shed. Visually inspected. Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	Communal areas	There are no communal areas.
Within the grounds, there is a timber and felt garden shed. Visually inspected. The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	permanent	
Outside areas and boundaries The property benefits from a corner plot with garden grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.	outbuildings	Within the grounds, there is a timber and felt garden shed.
grounds to the front, side and rear which are mainly laid to a combination of grass, paving, patio and driveway. Boundaries are formed in timber post and panel fencing or hedges.		Visually inspected.
hedges.		grounds to the front, side and rear which are mainly laid to a
Visually inspected.		, · · · · · · · · · · · · · · · · · · ·
		Visually inspected.

	•
Ceilings	Ceilings are plasterboard lined.
	Visually inspected from floor level.
Internal walls	Internal walls and partitions are plasterboard lined.
	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
Floors including sub floors	Flooring at ground floor level is of a solid concrete construction and the upper floors are suspended timber.
	Due to the ground floor construction, there was no sub-floor/solum area to inspect.
	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
Internal joinery and kitchen fittings	Internal joinery, notably that of skirtings and door surrounds, are formed in painted moulded facings.
	Some of the internal doors have been replaced with oak panel units and there are some original white pressed, hollow core units.
	The kitchen has been re-fitted with modern units, incorporating an island feature, granite worktops and integrated sink, dishwasher, oven, gas hob and extractor hood.
	There is a timber built stair linking the ground and first floor accommodation.
	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
Chimney breasts and fireplaces	There are no chimney breasts or fireplaces.
Internal decorations	Internally, walls and ceiling linings are painted or tile clad. Visually inspected.
Cellars	There are no cellars.
Electricity	The property is connected to mains electricity supply.
	Distribution wiring is formed in PVC sheathed cabling with the power points being of the square pin/13 amp type. The circuitry is protected by a consumer board and the electric meter is fitted in the landing cupboard.

	Solar PV panels have been fitted to the front roof slope and we understand that this provides electricity for the house, with any balance being fed into the National Grid. The full details are available at the request of the vendor, but we understand the panels were installed by Cairngorm with a 10 year guarantee. Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will
	state that in the report and will not turn them on.
Gas	The property is connected to the mains gas supply.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Water, plumbing and	The property is connected to the mains water supply.
bathroom fittings	Distribution pipework is formed in copper and soil/wastepipes are formed in PVC.
	The en-suite shower room is fitted with a 3 piece white suite which includes WC, wash hand basin and shower with mixer fitting.
	The first floor bathroom is fitted with a 3 piece white suite which includes WC, wash hand basin and bath with mixer shower over.
	There is an external tap fitted at the side elevation.
	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
Heating and hot water	Space heating is provided via the Potterton Suprima boiler located in the utility which serves thermostatically radiators throughout the main living accommodation.
	Domestic hot water is via the central heating boiler and the hot water cylinder in the hall cupboard.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
Drainage	Drainage is connected to the main public sewer.

	Drainage covers etc were not lifted.	
	Neither drains nor drainage systems were tested.	
Fire, smoke and burglar alarms	Smoke alarms are fitted in the hall and landing.	
aidillis	There is a carbon monoxide detector which is fitted in the hallway.	
	Visually inspected.	
	No tests whatsoever were carried out to the system or appliances.	
Any additional limits to inspection	We did not inspect woodwork, services or other parts of the property which were covered, unexposed or inaccessible. This report cannot therefore comment that such parts of the property are free from defect.	
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.	

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	
Notes:	There was no indication of any structural movement affecting the property.

Dampness, rot and infestation	
Repair category:	
Notes:	No evidence of dampness, rot or infestations.

Chimney stacks	
Repair category:	
Notes:	Not applicable.

Roofing including roof space	
Repair category:	1
Notes:	No reportable defects.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Rainwater fittings	3
Repair category:	
Notes:	No reportable defects.

Main walls	
Repair category:	1
Notes:	Generally in satisfactory condition, although minor shrinkage cracking was noted to some pointing finishes at the front elevation. This is not considered significant.

Windows, external doors and joinery	
Repair category:	
Notes:	No reportable defects.

External decorations	
Repair category:	
Notes:	Externally, the property was found to be in satisfactory decorative order.

Conservatories /	porches
Repair category:	

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:	Not applicable.
Communal areas	
Repair category:	
Notes:	Not applicable.
Garages and permanent outbuildings	
Repair category:	
Notes:	Some flaking/blistering was noted to the rear door of the garage.

Outside areas and boundaries	
Repair category:	1
Notes:	Garden grounds were found to be suitably tended at the time of inspection.

Ceilings	
Repair category:	1
Notes:	No reportable defects.

Internal walls

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	No reportable defects.

Floors including sub-floors	
Repair category:	1
Notes:	No reportable defects.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	No reportable defects.

Chimney breasts and fireplaces	
Repair category:	
Notes:	Not applicable.

Internal decorations	
Repair category:	1
Notes:	Internally, the property was found to be in good decorative order.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Cellars	
Repair category:	
Notes:	Not applicable.

Electricity	
Repair category:	
Notes:	Although not specifically tested, no visual defects were apparent.
	Solar PV panels have the benefit of a Cairngorm 10 year guarantee.

Gas	
Repair category:	
Notes:	Although not specifically tested, no visual defects were apparent.

Water, plumbing and bathroom fittings	
Repair category:	
Notes:	Although not specifically tested, no visual defects were apparent.

Heating and hot water	
Repair category:	

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

	1
Notes:	There was no evidence of recent testing of the central heating system. In the absence of a recent service certificate, it would be prudent to have a registered contractor carry out a service to ensure its safe and efficient operation.

Drainage	
Repair category:	
Notes:	There was no surface indication of any defect noted.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	
Communal areas	
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	
Internal decorations	1
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground and first.
2. Are there three steps or fewer to a main entrance door of the property?	[x]YES []NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[x]YES []NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[]YES [x]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES []NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

We have assumed that the property possesses a good and valid title, and that the tenure is Standard or Absolute Ownership.

The property has been subject to internal alteration at ground floor level and we therefore assume that the relevant Local Authority consents can be made available for transfer.

Solar PV panels are fitted to the property. The relevant contract details and feed-in tariffs are available from the vendor, but the panels themselves are covered by the balance of a 10 year guarantee from Cairngorm.

Estimated re-instatement cost (£) for insurance purposes

285,000

TWO HUNDRED AND EIGHTY FIVE THOUSAND POUNDS

Valuation (£) and market comments

265,000

After full and careful consideration we are of the opinion that the current open Market Value of the heritable subjects as described and with the benefit of full vacant possession would be fairly stated in a figure of TWO HUNDRED AND SIXTY FIVE THOUSAND POUNDS.

We have endeavoured to reflect market conditions currently prevailing in arriving at our opinion of value.

Report author:	Keith Campbell, Assoc.RICS
Company name:	Inverness - Allied Surveyors Scotland Plc
Address:	Pavilion1 Fairways Business Park Inverness IV2 6AA
Signed:	Electronically Signed: 152596-640524C0-094F
	29/01/2020

Date of report:	

P A R T 2.

MORTGAGE VALUATION REPORT

Includes a market valuation of the property.





Property: 26 Spires Crescent Nairn IV12 5PZ Client: Mr. Anthony Cassar-Torreggiani Tenure: Ownership Scotland Date of Inspection: Reference: I/2188/KC/sf

This report has been prepared as part of your instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising your lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

The property forms part of an established residential area of similar style and age properties located on the fringes of Nairn, close to Nairn Dunbar Golf Club. All local amenities can be found nearby.

2.0 DESCRIPTION 2.1 Age: 15 year

The subjects comprise a detached one and half storey dwelling house having the benefit of surrounding garden grounds, off street parking and an attached single car garage.

3.0 CONSTRUCTION

Walls - cavity timber frame and rendered block or facing brick, plasterboard lined internally.

Roof - pitched and concrete tiled over timber trusses.

Floor - solid concrete and suspended timber.

4.0 ACCOMMODATION

The accommodation may be summarised as follows:

Ground Floor - Hall, Living Room, Kitchen/Dining Room, Utility, Bedroom and en-suite Shower Room.

First Floor - Landing, three Bedrooms and Bathroom.

5.0	SERVICES (No tests have been applied to any of the services)						
Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains sewer

Central Heati	ng:	Gas fired central heating system				
6.0	OUTBUILDIN	NGS				
Garage:		Attached single car garage.				
Others:		Timber shed.				
7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
The property vage and const		in a good state	of repair and de	ecoration, both internally and e	externally, havin	g regard to
8.0	ESSENTIAL I property)	REPAIR WORK	(as a condition	of any mortgage or, to preser	ve the condition	of the
None.						
8.1 Retention	recommended	d:	Not applicable).		
9.0	ROADS &FO	OTPATHS				
Made up and a	adopted by the	Local Authority.				
10.0	BUILDINGS I (£):	NSURANCE	285,000 GROSS EXTERNAL 149 Square metres			
	This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.					
11.0	GENERAL REMARKS					
We have assu Ownership.	We have assumed that the property possesses a good and valid title, and that the tenure is Standard or Absolute Ownership.					
		ct to internal alte be made availa		d floor level and we therefore a	ssume that the	relevant
	Solar PV panels are fitted to the property. The relevant contract details and feed-in tariffs are available from the vendor, but the panels themselves are covered by the balance of a 10 year guarantee from Cairngorm.					
VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.						
12.1	Market Value in present condition (£): TWO HUNDRED AND SIXTY FIVE THOUSAND POUNDS			AND		
12.2	Market Value on completion of essential					
26 Spires Creso	l ent Nairn IV/1	2 5P7				Page 2

	works (£):					
12.3 Suitable security for normal mortgage purposes?		Yes				
12.4	Date of Valua	ation:	28/01/2020			
Signature:	Signature: Electronically Signed: 152596-640524			6-640524C0-094F		
Surveyor:	Keith Campbell Assoc.RICS			Date:	29/01/2020	
Invernes	Inverness - Allied Surveyors Scotland Plc					
Office:	Pavilion1 Fairways Business Park Inverness IV2 6AA		Tel: 01463 239 494 Fax: email: inverness@alliedsur	rveyorsscotla	nd.com	

P A R T 3 .

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	26 Spires Crescent Nairn IV12 5PZ
Customer	Mr. Anthony Cassar-Torreggiani
Customer address	26 Spires Crescent Nairn IV12 5PZ
Prepared by	Keith Campbell, Assoc.RICS Inverness - Allied Surveyors Scotland Plc

Energy Performance Certificate (EPC)

Dwellings

Scotland

26 SPIRES CRESCENT, NAIRN, IV12 5PZ

Dwelling type:Detached houseDate of assessment:28 January 2020Date of certificate:29 January 2020

Total floor area: 133 m²

Primary Energy Indicator: 161 kWh/m²/year

Reference number: 2782-1002-9209-3000-2200 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,853	See your recommendations
Over 3 years you could save*	£390	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (81)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (78)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Condensing boiler	£2,200 - £3,000	£267.00
2 Solar water heating	£4,000 - £6,000	£123.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	****	★★★★ ☆
Roof	Pitched, insulated (assumed) Roof room(s), ceiling insulated	**** ****	**** ****
Floor	Solid, insulated (assumed)	_	_
Windows	Fully double glazed	****	★★★★ ☆
Main heating	Boiler and radiators, mains gas	****	★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	****	★★★★ ☆
Secondary heating	None	_	_
Hot water	From main system	****	****
Lighting	Low energy lighting in 94% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 29 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.7 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,136 over 3 years	£1,932 over 3 years	
Hot water	£423 over 3 years	£237 over 3 years	You could
Lighting	£294 over 3 years	£294 over 3 years	save £390
Totals	£2,853	£2,463	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

D	and the second s	Indiantive and	Typical saving	Rating after improvement			
RE	ecommended measures	Indicative cost	per year	Energy	Environment		
1	Replace boiler with new condensing boiler	£2,200 - £3,000	£89	B 83	B 81		
2	Solar water heating	£4,000 - £6,000	£41	B 85	B 83		

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

Micro CHP

Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

Solar photovoltaics

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	11,785	N/A	N/A	N/A
Water heating (kWh per year)	2,653			_

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Keith Campbell

Assessor membership number: EES/010338

Company name/trading name: Allied Surveyors Scotland Plc

Address: Lyle House, Pavilion 1 Fairways Business Park

Invernesshire Inverness IV2 6AA

Phone number: 01463 239 494

Email address: inverness@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



P A R T 4.

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Questionnaire

Property Address	26 Spires Crescent Nairn IV12 5PZ
Seller(s)	Anthony & Susan Cassar- Torreggiani
Completion date of property questionnaire	28/01/2020

Note for sellers

1.	Length of ownership	
	How long have you owned the p 14.5 Years	roperty?
2.	Council tax	
	Which Council Tax band is your []A []B []C []D [x]E []F []G []H	property in? (Please circle)
3.	Parking	
	What are the arrangements for parking at your property? (Please tick all that apply)	
	Garage	[x]
	Allocated parking space	[]
	Driveway	[x]
	Shared parking	[]
	On street	[]
	Resident permit	[]
	Metered parking	[]
	Other (please specify):	

IO ow
Ю
IO
IO
IO
IO
IO

property questionnaire

	Please give any guarantees which you received for this work to your solicitor or estate agent.	
7.	Central heating	
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	[x]YES []NO []Partial
	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	Gas-fired	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating system installed?	
	2005	
	(ii) Do you have a maintenance contract for the central heating system?	[x]YES []NO
	If you have answered yes, please give details of the company with which you have a maintenance contract	
	Scottish Gas	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	
	November 2019	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	[x]YES []NO
9.	Issues that may have affected your property	
а	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	[]YES [x]NO
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[]YES[]NO
b	Are you aware of the existence of asbestos in your property?	[]YES [x]NO []Don't know

	If you have answered yes, please give det	ails:		
10.	Services			
а	Please tick which services are connected to your property and give details of the supplier:			
	Services	Connected	S	Supplier
	Gas or liquid petroleum gas	Υ	TE	i-on
	Water mains or private water supply	Y	S	Scottish Water
	Electricity	Y	E	E-on
	Mains drainage	Y	S	Scottish Water
	Telephone	Y	Т	alk Talk
	Cable TV or satellite	N		
	Broadband	Υ	Т	alk Talk
b	Is there a septic tank system at your property? []YES [x]NO			
	If you have answered yes, please answer the two questions below:			
	(i) Do you have appropriate consents for the discharge from your septic tank? []YES[]NO []Don't know			
	(ii) Do you have a maintenance contract for your septic tank? []YES[]NO			
	If you have answered yes, please give details of the company with which you have a maintenance contract:			
11.	Responsibilities for shared or common areas			
а	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:			
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details: [x]YES []NO			
	Dunbar Reach Residents association - maintenance of common grounds. Cost about £30 per annum			
С	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?			

d	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details:	[]YES [x]NO
е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	[]YES [x]NO
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.) If you have answered yes, please give details:	[]YES [x]NO
12.	Charges associated with your property	
а	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[]YES [x]NO
b	Is there a common buildings insurance policy?	[]YES [x]NO []Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	
С	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please give details:	
С	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	[]YES[]NO
	If you have answered yes, these guarantees will be needed by	

property questionnaire

the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:

14.	Guarantees		
а	Are there any guarantees or warranties for any of the following:		
(i)	Electrical work	[]NO []YES [x]Don't know []With title deeds []Lost	
(ii)	Roofing	[]NO []YES [x]Don't know []With title deeds []Lost	
(iii)	Central heating	[]NO []YES [x]Don't know []With title deeds []Lost	
(iv)	National House Building Council(NHBC)	[]NO []YES [x]Don't know []With title deeds []Lost	
(v)	Damp course	[]NO []YES [x]Don't know []With title deeds []Lost	
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	[]NO []YES [x]Don't know []With title deeds []Lost	
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):		
С	Are there any outstanding claims under any of the guarantees listed above?	[]YES[]NO	
	If you have answered yes, please give details:		

15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years?	[]YES [x]NO []Don't know
	If you have answered yes, please give details:	
	Notices that affect your property	

property questionnaire

16.			
In the past three years have you ever received a notice:			
а	advising that the owner of a neighbouring property has made a planning application?	[]YES [x]NO	
b	that affects your property in some other way?	[]YES [x]NO	
С	that requires you to do any maintenance, repairs or improvements to your property?	[]YES [x]NO	
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.		

Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.		
Signature(s):	Anthony & Susan Cassar-Torreggiani	
Capacity:	[x]Owner []Legally Appointed Agent for Owner	
Date:	28/01/2020	